

## AlephObjects.com

3D Printers, Parts, and Plastics

+1-970-377-1111

shop@alephobjects.com

626 West 66th Street

Loveland, Colorado 80538



### Service Bulletin

**Affected product:**

TAZ 3, TAZ 2 (24v), TAZ 1 (24v) 3D printers

**Effective date:**

April 4<sup>th</sup>, 2014

**Service issue:**

Budaschnozzle Heater Resistor failure

**Indication:**

**Sudden failure of the Budaschnozzle Hot End heating resistor**

**Corrective Action:**

After a thorough investigation, we have determined that in some cases the default 24v firmware settings can cause the hot end heater resistor to fail over time. We have tested and verified a software-based solution. We are recommending that all TAZ 3 users upgrade the Marlin firmware with the update instructions found here: <https://ohai.lulzbot.com/workflow/marlin-resistor-update/service-bulletins/>

If you have any questions or would like assistance in upgrading the firmware, please do not hesitate to contact our support team using the contact information below.

1-970-377-1111 x610

Support@LulzBot.com